
























Piese / Article




Feronerie / Fittings




1








2



3




4





$D1 = D2 \Rightarrow 90^\circ$

5



6



7